


Nimonik

RACK INSPECTION REPORT- DONE ON AN ANDROID DEVICE


Download and Login

- Download the Nimonik App
- Sign in with designated username
 - Sign up publically
 - Purchase through RNW
- Download 'Barcode scanner Keyboard, Demo' by TEC-IT

Starting an Audit



- Select 'Audit Templates'
- Generally select 'Pallet Rack Inspection'- 'Create Audit' unless this is a special inspection



Create an Audit

3:05 PM

< New Audit

FACILITY

Cleveland Range +

TITLE

Pallet Rack Inspection X

SCOPE

Insert scope here...

AUDITOR

Select an auditor +


DATE OF AUDIT

November 4, 2015

STATUS LABELS


➤ Title the Audit and Facility, and enter any relevant information including the auditor and date

Create an Audit



➤ Select a category such as 'Assembly'

➤ Select one of the sub-categories such as 'missing/damaged safety pin' etc.



missing/damaged safety pin
General Requirement: There should be one pin per bracket approved by the manufacturer
Typical Status: remediate (amber)
Typical Corrective Action: install compatible safety pin

CSA A344 Requirement:
6.5.2 Where beam safety pins are replaced by bolts, the specification of the bolt and nut assembly should be approved by the manufacturer or noted in the documents referenced by clause 5.5.6.
6.5.4 Installers should ensure that beam safety pins or other mechanical devices are properly installed. In areas accessible to the public, it may be advisable to bolt the lower beam levels to discourage their unauthorized removal.
8.2.4 Missing or damaged beam safety pins should be replaced immediately with the original rack manufacturer's approved beam safety pin. Alternative fasteners can be used in place of safety pin but only where the size, material specification, and installation requirements are formally approved by the

Create an Audit

missing/damaged safety pin

Assembly

5

Immediate danger - put out of service

C00193473
General Requirement: There should be one pin per bracket approved by the manufacturer

Typical Status: remediate (amber)
Typical Corrective Action: install

- Fill out the fields according to the chart below
- Use the barcode reader to add the inspection ID easily

Immediate action details:


Findings

Add corrective action

Comments:

Field	Risk	Requirements	Additional Info	Findings	Corrective Action	Corrective Action Note	More Information
Information already filled in	0	General Requirement	Immediate Action Details	Findings	NA	Complete Corrective Action	Comments
Information to be Input	Either not used or rated on 1-9	Inspection ID (available from RNW)	Actions to be completed	Specific Location (i.e. Bay #)	Corrective Action	Recommended Repair if Known	Comments


Create an Audit




➤ Changing the dot colour to a different status puts the item in the report

➤ Blue dots are not going show in the reports

➤ If there are multiple items with the same category of issue, click the issue and select 'Duplicate'




Complete an Audit



- To finish the report, click the menu button and select complete
- Sign to confirm completion
- Click the menu button again and select complete
- The report will be sent to the login email address (personal or assigned)

The Report



- The final report will look like the images on the left
- In addition, an RNW report can be generated by RNW using this information if requested.